



HC71802666 [Oil Pump]

Instruction Guide

ATTENTION INSTALLER!

To reduce rotor scoring, OE changed to a new style housing w/ a larger bore for the outer rotor. The bore was enlarged by .014" and maximum housing to rotor clearance to .024". It allows for the use of the flat sided or round O-rings.